HP SitePrint Value Pack 2.1.0 Software Release

SW VP2.1.0 available on March 4th, 2024.

SW VP 2.1.0 New functionalities:

- Leica iCR70 Integration: Leica iCR70 will be available as a compatible RTS.
- Custom prisms: capability to create custom prisms for Robotic Total Station set up.
- Site Print Control Panel Localization: Control Panel will be accessible in English, French, Dutch, German, Japanese, Spanish and Catalan.
- New system errors (updated in Service Manual).

SW VP 2.1.0 Main improvements and fixes:

- Accuracy improvements.
- Fixed Nozzle health button disappearing in some situations.
- Fixed an issue were printing progress was lost in the UI.
- Fixed visual problems in the UI when switching orientations with specific tablet models.
- Fixed visual problems in the UI map when printing drawings in millimeters.

IMPORTANT: HP strongly recommends that all units are upgraded to the new firmware as soon as possible. Please use a 4G (LTE) or 3G+ (HSPA+) mobile network connection to ensure that the firmware upgrade takes less than 30 minutes to download.