HP SitePrint Value Pack 2.0 Software Release



SW VP2.0 available on January 16th, 2024.

SW VP 2.0 New functionalities that help you operate better:

- Productivity optimizations:
 - A new navigation algorithm improves robot trajectory during printing.
 - o Enhanced turning performance introduces new maneuvering capabilities.
 - o Improved landing maneuvers reduce the need for retry alignment attempts.
- SitePrint Cloud Update:
 - Reset Robot to Default Settings: Achieve robot restoration to initial settings through the fleet menu in the cloud.
 - Invoicing Model Selection: Users must designate invoicing preferences with each CAD upload.
 - Daily and Monthly Capping Accounting Reports: Cloud platform now displays printed and billable areas for projects exceeding caps.
 - SitePrint diagnostics package is automatically uploaded to the Cloud without manual extraction.
- Control Panel Alerts:
 - Get alerts for new available software updates in the control panel.
 - o Receive alerts for unlevelled LN-150 in the control panel.
 - After robot installation (assignment to a Company cloud account), an NPS survey is initiated.
- Control Panel Settings Page Update
 - Materials list in the control panel's Settings Page is now arranged from more to less ink firing.

SW VP 2.0 Main improvements and fixes:

- Fixed "searching robot" pop-up that was blocking the screen.
- Fixed Zoom Out issues in UI map.
- Fixed split lines that were skipped.
- Fixed an issue where skipped segments were inaccurately marked as printed in green, now accurately marked in yellow.

IMPORTANT: HP strongly recommends that all units are upgraded to the new firmware as soon as possible. Please use a 4G (LTE) or 3G+ (HSPA+) mobile network connection to ensure that the firmware upgrade takes less than 30 minutes to download.